The symbols in the mass production body welding diagrams and in the replacement illustrations carry following meaning:

〈Mass Production Body Welding Diagram〉

- ✳ : Spot welding
- ▽ : MIG welding
- × : 2-plate welding
- ⊗ : 3-plate welding
- ⊠ : 4-plate welding
- P= Spot welding pitch
  Unit: mm (in)
- ( ) The number of the spot welding

〈Replacement Illustration〉

- X : Spot welding
- ● : MIG welding

NOTE: The welding symbols in the illustrations don't show exact welding locations. For exact welding locations, refer to the mass production body welding diagrams.